


REPORT

DUPLICATE

TRUESDAIL LABORATORIES, INC.

CHEMISTS - MICROBIOLOGISTS - ENGINEERS
RESEARCH - DEVELOPMENT - TESTING14201 FRANKLIN AVENUE
TUSTIN, CALIF. 92680
AREA CODE 714 • 730-6239
AREA CODE 213 • 225-1564
FAX 714 • 730-6462

CLIENT **Douglas Aircraft Company**
Internal Mail Code 74-41
3855 Lakewood Blvd.
Long Beach, California 90846
SAMPLE **Attention: Ron Fornator**
Water from Stormdrain, Torrance Facility
P.O. No.: T & M 23465C

DATE May 20, 1991

RECEIVED April 26, 1991

LABORATORY NO. 46993

INVESTIGATION **Quarterly analysis as required by NPDES permit #CA0001414**

RESULTS

A one gallon grab sample was taken from the stormdrain at 11:00 a.m. on April 26, 1991 by a representative of Truesdail Laboratories, Inc.

pH, Units (EPA 150.1 7.8
Temperature, °F 65

<u>Parameter</u>	<u>Method</u>	<u>MILLIGRAMS PER LITER</u>	
		<u>Detection Limit</u>	<u>Concentration</u>
Suspended Solids	EPA 160.2	4.0	4.0
BOD	EPA 405.1	2.0	2.04
Oil and Grease	EPA 413.1	6.0	11.7

Respectfully submitted,
TRUESDAIL LABORATORIES, INC.

Brian C. Puncochar, Manager
Water and Waste Laboratory

This report applies only to the sample, or samples, investigated and is not necessarily indicative of the quality or condition of apparently identical or similar products. As a mutual protection to clients, the public and these Laboratories, this report is submitted and accepted for the exclusive use of the client to whom it is addressed and upon the condition that it is not to be used, in whole or in part, in any advertising or publicity matter without prior written authorization from these Laboratories.